

**The complete kit contains:**

- A re-usable joint mould.
- Mastersheath FR993 flexible resin.
- Mould release agent.
- HV EPR insulating tape.
- Electrical screening tape.
- PVC adhesive insulation tape.
- Adhesion promoter.
- Abrasive tape.
- Paint brush.
- EPR semi-conductive tape [6,6kV only].
- Installation Instruction.

Components are available separately.

<b>JOINT SELECTION GUIDE</b>				
<b>Kit Ref No</b>	<b>Cable OD [mm]</b>	<b>Cable Size sqmm</b>	<b>Joint Length</b>	<b>Voltage</b>
JMS-4	25 - 27	4	260	1,1kV
JMS-10	28 - 34	6 - 10	260	1,1kV
JMS-16	33 - 36	16	400	1,1kV
JMS-2535	41 - 50	25 - 35	400	1,1kV
JMS-50	51 - 55	50	550	1,1kV
JMS-70	55 - 59	70	585	1,1kV
JMS-95	60 - 65	95	520	1,1kV
<b>6,6kV</b>				
JMS11-2535	53 - 56	25 - 35	585	6,6kV
JMS11-50	56 - 65	50	520	6,6kV
JMS11-7095	65 - 70	70 - 95	640	6,6kV
JMS11-120	74 - 97	120	800	6,6kV
JMS11-185240	75 - 108	185 - 240	800	6,6kV

*Setting the Standards in Cable Jointing*