


Three core joint with galvanised armour wrap.

These joints are extremely user friendly to install and are supplied with all materials necessary to complete the joint with the exception of connectors [ferrules].

The joints are supplied complete with a solderless earth system, comprising of constant force springs, tinned copper earth braids, copper mesh tape, galvanised wire mesh tape and worm drive clamps.

Joints are also available with double sleeve configuration, as well as with a galvanised armour wrap, upon specific customer request.

JOINT SELECTION GUIDE:



<u>Legend:</u>	JHEJ Joints
Voltages:	11kV, 22kV, 33kV
No of cores	3 = 3 core, 1 = single core
Cable type	X = XLPE, P = PILC XP = Transition
Size range	11 & 22kV 1 = 16 : 50mm, 2 = 70 : 150mm 3 = 185 : 300mm
	33kV 1 = 35 : 70mm, 2 = 95 : 150mm 3 = 185 : 300mm

Setting the Standards in Cable Jointing